

EXHIBIT D

ADAM TAVITIAN		VEHICLE ID		MILES IN	MILES OUT	DATE/TIME IN	DATE OUT	INVOICE NO.
		153964		33346	33346	07/11/16 07:46	08/31/16	27859
VEHICLE DESCRIPTION						TAG NO.	STATUS	
2013 DODGE DART SXT ()						06673	COMPLETE	
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS	
104466							Cash	
HOME PHONE	WORK PHONE	CELL PHONE	STOCK NO.	SERV. ADV.			RO COMMENT	
				MARVIN MELARA (381)				

Totals

	Amount
Parts	\$14.40
SalesTax	\$1.30
Labor	\$1,717.12
Sublets	\$700.00
<hr/>	
TOTAL CREDIT CARD	\$2,432.82

WLS
PAID AUG 31 2016

Sh
PICKED UP

STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE

ADAM TAVITIAN		VEHICLE ID		MILES IN	MILES OUT	DATE/TIME IN	DATE OUT	INVOICE NO.
		153964		33346	33346	07/11/16 07:46	08/31/16	27859
VEHICLE DESCRIPTION						TAG NO.	STATUS	
2013 DODGE DART SXT ()						06673	COMPLETE	
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS	
104466							Cash	
HOME PHONE	WORK PHONE	CELL PHONE	STOCK NO.	SERV. ADV.			RO COMMENT	
				MARVIN MELARA (381)				

Line	Op-Code	Fail Code	Tech	Hours	Type	Amount
------	---------	-----------	------	-------	------	--------

C * Continued

Correction Verified customer concern clutch pedal stays on the floor and will not come back up. Per Chrysler request performed tsb 06 001 16 clutch pedal operation x62 extended warranty. Replaced clutch master cylinder and reservoir hose. After bleeding clutch lines pedal still was stuck down. Removed transmission out of vehicle for inspection. During inspection found throw out bearing coming apart and leaking. . Removed clutch disc for inspection found clutch worn out and signs of been overheating. Recommend clutch assembly and a throw out bearing. Customer declined repairs at this moment. Reinstalled clutch assembly and transmission.

Part Number	Description	Qty.	Unit Price	Ext. Price
4318080AC	FLUID BRAKE	2	\$7.20	\$14.40
Parts Total...				\$14.40
Line Total...				\$1,731.52

D +	7001	A99	Customer	\$0.00
-----	------	-----	----------	--------

Concern GLENDALE DODGE RENTAL

Sublet Code	Vendor Name	PO# / Description	
	ENTERPRISE RENT-A-CA	PO# 31868	\$700.00
Sublet Total...			\$700.00
Line Total...			\$700.00

E +	07	A16	Customer	\$0.00
-----	----	-----	----------	--------

Concern COOLING LEAK
Correction Customer declined repairs

Line Total...	\$0.00
---------------	--------

Warranty Claim Type: W	Authorization Code:	Service Cont No:
------------------------	---------------------	------------------



GLENDAL DODGE CHRYSLER JEEP

ELLIS FAMILY STORES

900 S. Brand Blvd. - Glendale, CA 91204
(818) 242-4161 Fax (818) 242-3202 Service Toll Free (800) 741-2899
www.glendalecj.com



27859

(*HAZARDOUS MATERIAL) Removal charge for all hazardous materials removed from your automobile that must be disposed of as a hazardous waste.
IMPORTANT: Removes all personal property and valuables from your vehicle. We do not assume responsibility for loss or damage for articles left in your vehicle.
Thank you for this opportunity to serve you. It is our aim to perform all the repairs requested on this repair order to your complete satisfaction. If you are not completely satisfied please contact us immediately.

ADAM TAVITIAN		VEHICLE ID		MILES IN	MILES OUT	DATE/TIME IN	DATE OUT	INVOICE NO.
		153964		33346	33346	07/11/16 07:46	08/31/16	27859
VEHICLE DESCRIPTION						TAG NO.	STATUS	
2013 DODGE DART SXT ()						06673	COMPLETE	
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS	
104466							Cash	
HOME PHONE	WORK PHONE	CELL PHONE	STOCK NO.	SERV. ADV.			RO COMMENT	
				MARVIN MELARA (381)				
ORIGINAL ESTIMATE \$ _____ REVISED ESTIMATE \$ _____ I _____ ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL AND/OR RECEIPT OF VEHICLE. X _____ ESTIMATED PRICE. X _____ BAR# AB 220501 EPA# CAL 000383239								
X _____								
Line	Op-Code	Fail Code	Tech	Hours	Type	Amount		
A *	0000		A16		Customer	\$0.00		
Concern Customer States SEE BELOW								
Correction CHRYSLER LEGAL INSPECTION FOR CLUTCH FAILURE								
Line Total...						\$0.00		
B *	05		A16		Customer	\$0.00		
Concern BRAKES-customer states hand brake not working chk and advice								
Cause RATCHET STRIPPED								
Correction REPLACED HAND BRAKE ASSEMBLY PER SERVICE CONTRACT								
AUTHORIZATION. RO 30279								
Line Total...						\$0.00		
C *	20		A16		Customer	\$1,717.12		
Concern MANUAL TRANSMISSION-customer states clutch pedal goes to floor will not go into gear								
Cause Verified customer concern clutch pedal stays on the floor and will not come back up. Per Chrysler request performed tsb 06 001 16 clutch pedal operation x62 extended warranty. Replaced clutch master cylinder and reservoir hose. After bleeding clutch lines pedal still was stuck down. Removed transmission out of vehicle for inspection. During inspection found throw out bearing coming apart and leaking. . Removed clutch disc for inspection found clutch worn out and signs of been overheating. Recommend clutch assembly and a throw out bearing. Customer declined repairs at this moment. Reinstalled clutch assembly and transmission.								